




# Compatible OS List

2020-09-15

HW	Windows						Linux		
	SW Package Part No.	Win7 32bit	Win7 64bit	Win8 32bit	Win8 64bit	Win10 32bit	Win10 64bit	SW Package Part No.	Kernel Ver.
									
<b>■ Camara Link</b>									
APX-3311	AZP-ACAP-02	○	○	-	-	②	②	-	-
APX-3302	AZP-ACAP-02	○	○	-	-	①	①	ALP-ACAP-02	Ver.4.18.0
APX-3307	AZP-ACAP-02	○	○	-	-	①	①	-	-
	AZP-FDK3307-01	○	○	-	-	-	①	-	-
APX-3323	AZP-ACAP-02	○	○	-	-	①	①	ALP-ACAP-02	Ver.4.18.0
APX-3327	AZP-ACAP-02	○	○	-	-	①	①	-	-
	AZP-FDK3327-01	○	○	-	-	-	①	-	-
APX-3324A	AZP-ACAP-02	○	○	-	-	①	①	ALP-ACAP-02	Ver.4.18.0
APX-3326A	AZP-ACAP-02	○	○	-	-	①	①	ALP-ACAP-02	Ver.4.18.0
<b>■ CoaXPress</b>									
APX-3664, APX-3664A, APX-3664A-E7	AZP-ACAPTF-01	○	○	-	-	①	①	ALP-ACAP-02	Ver.4.18.0
APX-3664G3	AZP-ACAPTF-01	○	○	-	-	①	①	-	-
APX-3664S4	AZP-ACAPTF-01	○	○	-	-	①	①	ALP-ACAP-02	Ver.4.18.0
APX-3636, APX-3636A	AZP-ACAPTF-01	○	○	-	-	①	①	-	-
APX-3634	AZP-ACAPTF-01	○	○	-	-	①	①	ALP-ACAP-02	Ver.4.18.0
APX-3662V2	AZP-ACAPTF-01	○	○	-	-	①	①	-	-
APX-3661	AZP-ACAPTF-01	○	○	-	-	①	①	-	-
APX-36124	AZP-ACAPTF-01	○	○	-	-	①	①	-	-
<b>■ Opt-C:Link</b>									
APX-3800	AZP-ACAPPLUS-01	○	○	-	-	①	①	ALP-ACAP-02	Ver.4.18.0
APX-3800X2	AZP-ACAPPLUS-01	○	○	-	-	①	①	-	-
APX-3841	AZP-ACAPPLUS-01	○	○	-	-	①	①	-	-
<b>■ USB3</b>									
APX-3424	-	○	○	○	○	○	○	-	-
<b>■ GigE</b>									
APX-3404	-	○	○	-	-	-	-	-	-
APX-3404 -I350	-	○	○	○	○	②	②	-	-
APX-3442	-	-	○	-	○	-	②	-	-
<b>■ Analog</b>									
APC-335	AZP-335-01	○	-	-	-	-	-	-	-
APC-3310BRT	AZP-3310-01	○	-	-	-	-	-	-	-
APC-3322B	AWP-3322A-01	○	-	-	-	-	-	-	-
APX-3502	AZP-ACAPPLUS-01	○	○	-	-	②	②	-	-
APX-3504	AZP-ACAPPLUS-01	○	○	-	-	②	②	ALP-ACAP-02	Ver.4.18.0
<b>■ Digital I/F</b>									
APX-3302-LV	AZP-ACAP-02	○	○	-	-	①	①	-	-
<b>■ COM Express Board</b>									
ASI-1300T6 Series	AZP-ACAP-02	○	○	-	-	-	-	ALP-ACAP-02	Ver.4.18.0
ASI-1300optT6 Series	AZP-ACAPPLUS-01	○	○	-	-	-	-	ALP-ACAP-02	Ver.4.18.0
ASI-1300SL Series	AZP-ACAP-02	-	-	-	-	-	○	-	-
ASI-1300optSL Series	AZP-ACAPPLUS-01	-	-	-	-	-	○	-	-
ASI-1424SL/ASI-1426SL	AZP-ACAP-02	-	-	-	-	-	○	-	-
ASI-1364S4	AZP-ACAPTF-01	-	-	-	-	-	○	-	-
<b>■ Intelligent License</b>									
ALI-6000(F)-01	AZP-ALI-SV	○	-	-	-	-	-	-	-
ALI-7000(F)-01	AZP-ALI-SV	○	-	-	-	-	-	-	-
AML-0881 (APX-3881)	AZP-AML-01	○	○	-	-	-	-	-	-
AML-1681 (APX-3881)	AZP-AML-01	○	○	-	-	-	-	-	-
									
APX-520	AWP-520-01	○	○	-	-	①	①	-	-
APX-5040	AWP-ADCSDK2-01	○	○	-	-	①	①	ALP-ADCSDK2-01	Ver.3.11.6-4
APX-5200 / APX-5360	AWP-5200-01	○	○	-	-	①	①	ALP-5200-01	Ver.3.11.6-4
APX-5056	AZP-ADAQ-01	○	○	-	-	①	①	-	-
ADO-1616	AWP-ADO1616-01	○	○	-	-	①	①	-	-
									
APC-732A-2G, 732A-4G	AWP-730-01	○	○	○	○	-	-	ALP-730-01	Ver.3.10.0
APX-721LP1	AWP-730-01	○	○	○	○	-	-	ALP-730-01	Ver.3.10.0
APX-721B	AWP-730-01	○	○	-	-	②	②	ALP-730-01	Ver.3.10.0
APX-741B, 742B	AWP-741-01	○	○	-	-	②	②	ALP-741-01	Ver.5.4.0
APX-941LP4	AWP-730-02	○	○	○	○	②	②	ALP-730-03	Ver.2.6.32
APX-781/782	AWP-781-01	○	○	○	○	①	①	ALP-781-01	Ver.4.18.0
APX-7102	AWP-7102-01	-	-	-	-	-	-	ALP-7102-01	Ver.2.6.25
APX-7142	AWP-7140-01	○	○	○	○	②	②	ALP-7140-01	Ver.4.15.0
APX-7402	AWP-7400-01	○	○	-	○	②	②	ALP-7402-01	Ver.3.10.0

※Description of the mark and color

○ : Suported, - : Not supported, Grey : 3rd party Software, Orange : Discontinued

※In case of operation in Windows10, following action is required.

① : Disable fast startup ② : Disable fast startup or Secure boot

※If you want to use a higher Kernel version in Linux than the version indicated above, please consult with your sales contact in advance.